

TO: Dr. Mike Riggle

FROM: Rosanne Williamson

RE: FOIA Requests

FOIA Response:

Please see the attached email response. Responsive documents can be found online at <http://il.glenbrook.schoolboard.net/board>. (Responsive documents will not be attached to the all documents pdf, but can be found under the FOIA agenda item.)

Background:

The Freedom of Information Act (FOIA - 5 ILCS 140/1 et seq.) is a state statute that provides the public the right to access government documents and records. A person can ask a public body for a copy of its records on a specific subject and the public body must provide those records, unless there is an exemption in the statute that protects those records from disclosure (for example: records containing information concerning student records or personal privacy).

A public body must respond to a FOIA request within 5 business days after the public body receives the request or 21 business days if the request is for commercial purpose. That time period may be extended for an additional 5 business days from the date of the original due date if:

- The requested information is stored at a different location;
- The request requires the collection of a substantial number of documents;
- The request requires an extensive search;
- The requested records have not been located and require additional effort to find;
- The requested records need to be reviewed by staff who can determine whether they are exempt from FOIA;
- The requested records cannot be produced without unduly burdening the public body or interfering with its operations; or
- The request requires the public body to consult with another public body who has substantial interest in the subject matter of the request.

If additional time is needed, the public body must notify the requester in writing within 5 business days after the receipt of the request of the statutory reasons for the extension and when the requested information will be produced.



Elaine Geallis <egeallis@glenbrook225.org>

Re: RPZ devices

1 message

Rosanne Marie Williamson <rwilliamson@glenbrook225.org>

Thu, Dec 20, 2018 at 11:40 AM

To: Denise Burton <deniseb@bishopplumbing.com>

Bcc: egeallis@glenbrook225.org

Dear Ms. Burton,

Thank you for writing to Glenbrook High School District 225 with your request for information pursuant to the Illinois Freedom of Information Act, 5 ILCS 140/1 et seq.

On 12/14/18 we received your request for the following information:

We are requesting a list of RPZ devices in the school district (for both schools)

District Response: See attached.

Sincerely,

Rosanne Williamson Ed.D.
Assistant Superintendent for Educational Services
Glenbrook H.S. District 225
3801 West Lake Ave.
Glenview, IL 60026
847-486-4701


On Fri, Dec 14, 2018 at 1:06 PM Denise Burton <deniseb@bishopplumbing.com> wrote:

We are requesting a list of RPZ devices in the school district (for both schools)

Please send [to:deniseb@bishopplumbing.com](mailto:deniseb@bishopplumbing.com)

Thank you,
Denise Burton

2 attachments

 **RPZs 2018 - GBN.pdf**
191K

 **GBS RPZ.pdf**
618K

Glenbrook High Schools District 225 RPZ List

Glenbrook North HS – 2300 Shermer Rd Northbrook – 16 Total Devices on site

| | |
|-----------------------------------|---|
| ¾" Watts 909 Serial #480879 | Location: "A" Fan Room – Ceiling |
| ¾" Watts 009m3 Serial #91596 | Location: Music Room Attic |
| 4" Watts 909 Serial #201920 | Location: Pool Pump Room |
| 6" Ames 5000SS Serial #1012271001 | Location: Basement Pool Pump Room |
| ¾" Ames 4000B Serial #03651 | Location: Basement Pool Pump Room |
| ½" Watts 995 Serial #01336 | Location: Green House |
| 6" Ames 300SS Serial #3JL1365 | Location: Mech Room Between B116-B118 |
| ¾" Watts 007M2 Serial #93593 | Location: Mech Room Between B116-B118 |
| ¾" Watts 909 Serial #525572 | Location: Field House Tunnel |
| ¾" Febco 8254 Serial #W1445 | Location: Field House Tunnel |
| 1" Conbraco 40205A2 Serial #HJ214 | Location: Basement Chiller Room |
| ¾" Watts 909 Serial #414738 | Location: Basement Boiler Room |
| 1" Watts 009 Serial #108330 | Location: Basement Boiler Room by Softner |
| 1 ½" Watts 009M2 Serial #69828 | Location: Basement Boiler Room |
| 4" Watts 909 Serial #209753 | Location: Basement Boiler Room |
| 6" Febco 860 Serial #F0402031603 | Location: Field House by Football Field |

Glenbrook Off Campus Center - 1835 Landwehr Rd Glenview – 5 Total Devices on site

| | |
|-----------------------------------|--------------------------------|
| 3" Wilkins 375 AST Serial #5383 | Location: Sprinkler Room |
| 1 ½" Watts 009M2 Serial #136670 | Location: Sprinkler Room |
| 4" Wilkins 350 ADA Serial #V24528 | Location: Sprinkler Room |
| ¾" Wilkins 950XL Serial #3208000 | Location: Sprinkler Room |
| ¾" Watts 909 Serial #632582 | Location: Basement Boiler Room |

Glenbrook South High School 4000 W Lake Ave Glenview – 10 Total Devices on site

| | |
|-----------------------------------|---|
| 2" Febco 8254 Serial #A11433 | Location: Hot Box by Football Field |
| 1 ½" Febco 8254A Serial #015619 | Location: Hot Box by Football Field |
| 6" Watts 909 Serial #254895 | Location: Auto Shop |
| 1" Conbraco 40205A2 Serial #HJ216 | Location: Chiller Room |
| 1" Conbraco 40205A2 Serial #HJ220 | Location: Boiler Room |
| 1 ½" Watts 909 Serial #624359 | Location: Pool Room 2 nd Floor |
| 3" Watts 909 Serial #178913 | Location: Pool Filler Room |
| ½" Watts 009 Serial #A09139 | Location: Room 314 |
| 6" Ames 5000SS Serial #0115770601 | Location: Room 542 |
| ¾" Ames 4000B Serial #00022493 | Location Room 542 |

Village of Glenview



Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
Contact Name: **Kimberly Ptak**
Property Address: **4000 W Lake Ave
Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **825**
Size: **2"** Serial#: **A11433**
Manufacturer: **Febco** Hazard: **Irrigation**
Location: **football Field**
Reason for test: new existing replaced.

PASS

Test Date: 2018-04-25

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 7.4 (X) Closed Tight/Held () Leaked | Check Valve #2 5.8 (X) Closed Tight/Held () Leaked | Relief Valve 3.3 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 7.4 (X) Closed Tight/Held () Leaked | Check Valve #2 5.8 (X) Closed Tight/Held () Leaked | Relief Valve 3.3 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Halloran, Thomas**
Tester License Expiration: **05-31-2019**
Certification#: **XC1391**
Test Kit Serial #: **02081955**
Test Kit Date Tested for Accuracy: **01-22-2018**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **Halloran & Yauch, Inc.**
Phone: **(847) 281-9400**
Address: **28322 Ballard Drive
Lake Forest, IL 60045-**

Village of Glenview



Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
Contact Name: **Kimberly Ptak**
Property Address: **4000 W Lake Ave
Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **909**
Size: **1 1/2"** Serial#: **624359**
Manufacturer: **Watts** Hazard: **Domestic**
Location: **Pool Room, 2nd Floor**
Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 7.8 (X) Closed Tight/Held () Leaked | Check Valve #2 7.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.6 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 7.8 (X) Closed Tight/Held () Leaked | Check Valve #2 7.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.6 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Mills, Dave**
Tester License Expiration: **05-31-2019**
Certification#: **xc3901**
Test Kit Serial #: **05142957**
Test Kit Date Tested for Accuracy: **05-01-2018**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **Santucci Plumbing Inc**
Phone: **(847) 272-3090**
Address: **1855 Janke Dr.
Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **4000B**
 Size: **3/4"** Serial#: **0002493**
 Manufacturer: **Ames** Hazard: **Fire Bypass**
 Location: **Room 542**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|---|---|--|
| Check Valve #1 6.4 <input checked="" type="checkbox"/> Closed Tight/Held <input type="checkbox"/> Leaked | Check Valve #2 6.2 <input checked="" type="checkbox"/> Closed Tight/Held <input type="checkbox"/> Leaked | Relief Valve 2.0 <input checked="" type="checkbox"/> Opened <input type="checkbox"/> Did Not Open |
| Final Test | | |
| Check Valve #1 6.4 <input checked="" type="checkbox"/> Closed Tight/Held <input type="checkbox"/> Leaked | Check Valve #2 6.2 <input checked="" type="checkbox"/> Closed Tight/Held <input type="checkbox"/> Leaked | Relief Valve 2.0 <input checked="" type="checkbox"/> Opened <input type="checkbox"/> Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:
(no comments)

Tester Information

Tester Name: **Mills, Dave**
 Tester License Expiration: **05-31-2019**
 Certification#: **xc3901**
 Test Kit Serial #: **05142957**
 Test Kit Date Tested for Accuracy: **05-01-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Santucci Plumbing Inc**
 Phone: **(847) 272-3090**
 Address: **1855 Janke Dr.
 Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **909**
 Size: **3"** Serial#: **178913**
 Manufacturer: **Watts** Hazard: **Domestic**
 Location: **Pool Filter Room, makeup**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 7.0 (X) Closed Tight/Held () Leaked | Check Valve #2 6.8 (X) Closed Tight/Held () Leaked | Relief Valve 2.2 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 7.0 (X) Closed Tight/Held () Leaked | Check Valve #2 6.8 (X) Closed Tight/Held () Leaked | Relief Valve 2.2 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:
(no comments)

Tester Information

Tester Name: **Mills, Dave**
 Tester License Expiration: **05-31-2019**
 Certification#: **xc3901**
 Test Kit Serial #: **05142957**
 Test Kit Date Tested for Accuracy: **05-01-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Santucci Plumbing Inc**
 Phone: **(847) 272-3090**
 Address: **1855 Janke Dr.
 Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **825**
 Size: **1 1/2"** Serial#: **A015619**
 Manufacturer: **Febco** Hazard: **Irrigation**
 Location: **Football Field**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-04-25

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 7.6 (X) Closed Tight/Held () Leaked | Check Valve #2 6.6 (X) Closed Tight/Held () Leaked | Relief Valve 3.3 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 7.6 (X) Closed Tight/Held () Leaked | Check Valve #2 6.6 (X) Closed Tight/Held () Leaked | Relief Valve 3.3 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:
(no comments)

Tester Information

Tester Name: **Halloran, Thomas**
 Tester License Expiration: **05-31-2019**
 Certification#: **XC1391**
 Test Kit Serial #: **02081955**
 Test Kit Date Tested for Accuracy: **01-22-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Halloran & Yauch, Inc.**
 Phone: **(847) 281-9400**
 Address: **28322 Ballard Drive
 Lake Forest, IL 60045-**

Village of Glenview



Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave**
Glenview, IL 60026

Assembly Information

Type: **RP**
 Size: **1/2"**
 Manufacturer: **Watts**
 Location: **2nd floor north mens bathroom janitors closet -soap dispenser**
 Reason for test: new existing replaced.

Model #: **009**
 Serial#: **183954**
 Hazard: **Domestic**

PASS

Test Date: 2018-08-13

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 9.2 (X) Closed Tight/Held () Leaked | Check Valve #2 9.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.6 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 9.2 (X) Closed Tight/Held () Leaked | Check Valve #2 9.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.6 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Butler, Jr., Alfred J.**
 Tester License Expiration: **05-31-2019**
 Certification#: **XC4202**
 Test Kit Serial #: **0087408**
 Test Kit Date Tested for Accuracy: **08-23-2018**
 Test Kit Mfr. & Mod. #: **Watts TK99E**
 Testing Co Name: **DeFranco Plumbing, Inc.**
 Phone: **(847) 438-0808**
 Address: **20330 N. Rand Road**
Palatine, IL 60074

Village of Glenview



Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **009**
 Size: **1/2"** Serial#: **183957**
 Manufacturer: **Watts** Hazard: **Domestic**
 Location: **2nd floor south end near janitors closet - soap dispenser**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-09-13

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 9.6 (X) Closed Tight/Held () Leaked | Check Valve #2 9.2 (X) Closed Tight/Held () Leaked | Relief Valve 3.6 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 9.6 (X) Closed Tight/Held () Leaked | Check Valve #2 9.2 (X) Closed Tight/Held () Leaked | Relief Valve 3.6 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Butler, Jr., Alfred J.**
 Tester License Expiration: **05-31-2019**
 Certification#: **XC4202**
 Test Kit Serial #: **0087408**
 Test Kit Date Tested for Accuracy: **08-23-2018**
 Test Kit Mfr. & Mod. #: **Watts TK99E**
 Testing Co Name: **DeFranco Plumbing, Inc.**
 Phone: **(847) 438-0808**
 Address: **20330 N. Rand Road
 Palatine, IL 60074**

Village of Glenview



Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
Contact Name: **Kimberly Ptak**
Property Address: **4000 W Lake Ave
Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **909**
Size: **6"** Serial#: **254895**
Manufacturer: **Watts** Hazard: **Domestic**
Location: **Auto Shop**
Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 6.8 (X) Closed Tight/Held () Leaked | Check Valve #2 6.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.2 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 6.8 (X) Closed Tight/Held () Leaked | Check Valve #2 6.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.2 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:
(no comments)

Tester Information

Tester Name: **Mills, Dave**
Tester License Expiration: **05-31-2019**
Certification#: **xc3901**
Test Kit Serial #: **05142957**
Test Kit Date Tested for Accuracy: **05-01-2018**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **Santucci Plumbing Inc**
Phone: **(847) 272-3090**
Address: **1855 Janke Dr.
Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **40-20**
 Size: **1"** Serial#: **HJ216**
 Manufacturer: **Conbraco** Hazard: **Domestic**
 Location: **Chiller Room**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 7.8 (X) Closed Tight/Held () Leaked | Check Valve #2 7.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.6 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 7.8 (X) Closed Tight/Held () Leaked | Check Valve #2 7.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.6 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Mills, Dave**
 Tester License Expiration: **05-31-2019**
 Certification#: **xc3901**
 Test Kit Serial #: **05142957**
 Test Kit Date Tested for Accuracy: **05-01-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Santucci Plumbing Inc**
 Phone: **(847) 272-3090**
 Address: **1855 Janke Dr.
 Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RPDA** Model #: **5000SS**
 Size: **6"** Serial#: **0115770601**
 Manufacturer: **Ames** Hazard: **Fire Protection**
 Location: **Room 542**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 6.4 (X) Closed Tight/Held () Leaked | Check Valve #2 3.2 (X) Closed Tight/Held () Leaked | Relief Valve 2.0 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 6.4 (X) Closed Tight/Held () Leaked | Check Valve #2 3.2 (X) Closed Tight/Held () Leaked | Relief Valve 2.0 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:
(no comments)

Tester Information

Tester Name: **Mills, Dave**
 Tester License Expiration: **05-31-2019**
 Certification#: **xc3901**
 Test Kit Serial #: **05142957**
 Test Kit Date Tested for Accuracy: **05-01-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Santucci Plumbing Inc**
 Phone: **(847) 272-3090**
 Address: **1855 Janke Dr.
 Northbrook, IL 60062**

Village of Glenview



Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
Contact Name: **Kimberly Ptak**
Property Address: **4000 W Lake Ave
Glenview, IL 60026**

Assembly Information

Type: **RP**
Size: **1/2"**
Manufacturer: **Watts**
Location: **1st floor in mens bathroom janitors closet -soap dispenser**
Reason for test: new existing replaced.

Model #: **009**
Serial#: **183398**
Hazard: **Domestic**

PASS

Test Date: 2018-08-13

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 9.2 (X) Closed Tight/Held () Leaked | Check Valve #2 9.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.4 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 9.2 (X) Closed Tight/Held () Leaked | Check Valve #2 9.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.4 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Butler, Jr., Alfred J.**
Tester License Expiration: **05-31-2019**
Certification#: **XC4202**
Test Kit Serial #: **0087408**
Test Kit Date Tested for Accuracy: **08-23-2018**
Test Kit Mfr. & Mod. #: **Watts TK99E**
Testing Co Name: **DeFranco Plumbing, Inc.**
Phone: **(847) 438-0808**
Address: **20330 N. Rand Road
Palatine, IL 60074**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **009**
 Size: **1/2"** Serial#: **A09139**
 Manufacturer: **Watts** Hazard: **Domestic**
 Location: **Roomm 314, DI water
 makeup**

PASS

Test Date: 2018-07-02

Reason for test: new existing replaced.

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 8.2 (X) Closed Tight/Held () Leaked | Check Valve #2 8.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.2 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 8.2 (X) Closed Tight/Held () Leaked | Check Valve #2 8.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.2 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Mills, Dave**
 Tester License Expiration: **05-31-2019**
 Certification#: **xc3901**
 Test Kit Serial #: **05142957**
 Test Kit Date Tested for Accuracy: **05-01-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Santucci Plumbing Inc**
 Phone: **(847) 272-3090**
 Address: **1855 Janke Dr.
 Northbrook, IL 60062**

The above tester certifies that all information submitted for this report is true and accurate
 The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **009**
 Size: **3/4"** Serial#: **186267**
 Manufacturer: **Watts** Hazard: **Domestic**
 Location: **boiler makeup for pool - pool mech rm**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-08-13

Assembly Test Information

| Initial Test | | |
|---|--|---|
| Check Valve #1 10.0 (X) Closed Tight/Held () Leaked | Check Valve #2 9.8 (X) Closed Tight/Held () Leaked | Relief Valve 3.5 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 10.0 (X) Closed Tight/Held () Leaked | Check Valve #2 9.8 (X) Closed Tight/Held () Leaked | Relief Valve 3.5 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Butler, Jr., Alfred J.**
 Tester License Expiration: **05-31-2019**
 Certification#: **XC4202**
 Test Kit Serial #: **0087408**
 Test Kit Date Tested for Accuracy: **08-23-2018**
 Test Kit Mfr. & Mod. #: **Watts TK99E**
 Testing Co Name: **DeFranco Plumbing, Inc.**
 Phone: **(847) 438-0808**
 Address: **20330 N. Rand Road
 Palatine, IL 60074**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
Contact Name: **Kimberly Ptak**
Property Address: **4000 W Lake Ave
Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **40-20**
Size: **1"** Serial#: **HJ220**
Manufacturer: **Conbraco** Hazard: **Domestic**
Location: **Boiler Room, North Wall**
Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 7.8 (X) Closed Tight/Held () Leaked | Check Valve #2 7.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.6 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 7.8 (X) Closed Tight/Held () Leaked | Check Valve #2 7.6 (X) Closed Tight/Held () Leaked | Relief Valve 2.6 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Mills, Dave**
Tester License Expiration: **05-31-2019**
Certification#: **xc3901**
Test Kit Serial #: **05142957**
Test Kit Date Tested for Accuracy: **05-01-2018**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **Santucci Plumbing Inc**
Phone: **(847) 272-3090**
Address: **1855 Janke Dr.
Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
 Contact Name: **Kimberly Ptak**
 Property Address: **4000 W Lake Ave
 Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **975**
 Size: **2"** Serial#: **4405602**
 Manufacturer: **Wilkins** Hazard: **Domestic**
 Location: **football field concession stand mechanical room**
 Reason for test: new existing replaced.

PASS

Test Date: 2018-07-02

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 9.0 (X) Closed Tight/Held () Leaked | Check Valve #2 8.4 (X) Closed Tight/Held () Leaked | Relief Valve 3.2 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 9.0 (X) Closed Tight/Held () Leaked | Check Valve #2 8.4 (X) Closed Tight/Held () Leaked | Relief Valve 3.2 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Mills, Dave**
 Tester License Expiration: **05-31-2019**
 Certification#: **xc3901**
 Test Kit Serial #: **05142957**
 Test Kit Date Tested for Accuracy: **05-01-2018**
 Test Kit Mfr. & Mod. #: **Mid-West 845-5**
 Testing Co Name: **Santucci Plumbing Inc**
 Phone: **(847) 272-3090**
 Address: **1855 Janke Dr.
 Northbrook, IL 60062**

Backflow Prevention Assembly Test and Maintenance Report

Customer Information

Customer / Property Name: **D225 Glenbrook South High School**
Contact Name: **Kimberly Ptak**
Property Address: **4000 W Lake Ave
Glenview, IL 60026**

Assembly Information

Type: **RP** Model #: **009**
Size: **1/2"** Serial#: **184023**
Manufacturer: **Watts** Hazard: **Domestic**
Location: **1st floor south mens janitors closet soap dispenser**
Reason for test: new existing replaced.

PASS

Test Date: 2018-08-13

Assembly Test Information

| Initial Test | | |
|--|--|---|
| Check Valve #1 9.3 (X) Closed Tight/Held () Leaked | Check Valve #2 9.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.3 (X) Opened () Did Not Open |
| Final Test | | |
| Check Valve #1 9.3 (X) Closed Tight/Held () Leaked | Check Valve #2 9.0 (X) Closed Tight/Held () Leaked | Relief Valve 3.3 (X) Opened () Did Not Open |

As the tester of record, I affirm this test as: Passed Failed **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Butler, Jr., Alfred J.**
Tester License Expiration: **05-31-2019**
Certification#: **XC4202**
Test Kit Serial #: **0087408**
Test Kit Date Tested for Accuracy: **08-23-2018**
Test Kit Mfr. & Mod. #: **Watts TK99E**
Testing Co Name: **DeFranco Plumbing, Inc.**
Phone: **(847) 438-0808**
Address: **20330 N. Rand Road
Palatine, IL 60074**



Elaine Geallis <egeallis@glenbrook225.org>

Re: FOIA REQUEST - Donnelly

1 message

Rosanne Marie Williamson <rwilliamson@glenbrook225.org>

Tue, Jan 8, 2019 at 2:20 PM

To: donnellymike6@gmail.com

Bcc: egeallis@glenbrook225.org

Dear Mr. Donnelly,

Thank you for writing to Glenbrook High School District 225 with your request for information pursuant to the Illinois Freedom of Information Act, 5 ILCS 140/1 et seq.

On 12/31/18 we received your request for the following information:

As of 12/31/18:

- 1. Total Full-time Teachers / Instructors

District Response: 476

- 2. Total Full-time Other Staff

District Response: 341

- 3. Total Full-time Staff (presumed to equal #1 PLUS #2 above)

District Response: 817

For the Calendar Years (Jan – Dec) 2015, 2016, 2017 and 2018:

- 1. The name of any and all lawyers/law firms that represent(ed) your organization

District Response:

| |
|---|
| Engler Callaway Baasten and Sraga LLC |
| Hauser Izzo LLC |
| Hodges Loizzi Eisenhammer Rodick & Kohn LLP |
| Kriha Law LLC |
| Scariano, Himes And Petrarca |

- 2. The hourly rate(s) these lawyers/law firms charge(d) your organization during each calendar year

District Response:

Below are the most recent hourly rates for each of our attorneys:





| | |
|---|-------|
| Engler Callaway Baasten and Sraga LLC | \$220 |
| Hauser Izzo LLC | \$210 |
| Hodges Loizzi Eisenhammer Rodick & Kohn LLP | \$240 |
| Kriha Law LLC | \$270 |
| Scariano, Himes And Petrarca | \$255 |

3. The annual amount for money your organization paid each of these lawyers/law firms during each calendar year





District Response:

Our calendar spend for each of our attorneys is as follows:





- Engler Callaway Baasten and Sruga LLC

| | ↓ Calendar Year | Total Payments Amount |
|---|-----------------------|--------------------------|
|  | 2018 | 27,476.43 |
|  | 2017 | 29,460.32 |
|  | 2016 | 29,988.60 |
|  | 2015 | 61,314.21 |

- Hauser Izzo LLC

| | ↓ Calendar Year | Total Payments Amount |
|--|-----------------------|--------------------------|
|  | 2018 | 88,965.21 |
|  | 2017 | 50,841.00 |
|  | 2016 | 78,750.00 |
|  | 2015 | 86,301.60 |

- Hodges Loizzi Eisenhammer Rodick & Kohn LLP

| | ↓ Calendar Year | Total Payments Amount |
|---|-----------------------|--------------------------|
|  | 2018 | 53.00 |
|  | 2017 | 2,785.28 |
|  | 2016 | 9,288.17 |
|  | 2015 | 2,458.14 |

- Kriha Law LLC

| | ↓ Calendar Year | Total Payments Amount |
|---|-----------------------|--------------------------|
| ↻ | 2018 | 1,998.00 |

- Scariano, Himes And Petrarca

| | ↓ Calendar Year | Total Payments Amount |
|---|-----------------------|--------------------------|
| ↻ | 2018 | 224,226.93 |
| ↻ | 2017 | 265,492.83 |
| ↻ | 2016 | 81,974.12 |
| ↻ | 2015 | 139,038.57 |

Sincerely,

Rosanne Williamson Ed.D.
 Assistant Superintendent for Educational Services
 Glenbrook H.S. District 225
[3801 West Lake Ave.](#)
[Glenview, IL 60026](#)
 847-486-4701

On Wed, Jan 2, 2019 at 8:05 AM Michael Riggle <mriggle@glenbrook225.org> wrote:
 FYI. FOIA request.

----- Forwarded message -----
 From: **Mike Donnelly** <donnellymike6@gmail.com>
 Date: Mon, Dec 31, 2018 at 12:19 AM
 Subject: FOIA REQUEST
 To: <mriggle@glenbrook225.org>

Good evening,

This is a request for information under the Freedom of Information Act.

My request is not for commercial purposes and I am requesting the information be sent to me via email to save both your organization and me time and expense.

I understand you by law are given a reasonable amount of time to produce the information requested; if you can't produce the information in that time frame, please let me know when I can expect to receive it.

Below is the information I am requesting:

As of 12/31/18:

1. Total Full-time Teachers / Instructors
2. Total Full-time Other Staff

3. Total Full-time Staff (presumed to equal #1 PLUS #2 above)

For the Calendar Years (Jan – Dec) 2015, 2016, 2017 and 2018:

1. The name of any and all lawyers/law firms that represent(ed) your organization
2. The hourly rate(s) these lawyers/law firms charge(d) your organization during each calendar year
3. The annual amount for money your organization paid each of these lawyers/law firms during each calendar year

My strong preference is to receive the information in a Table format, like that you see in the below example (**items in Red Text are example info**).

If you are unable to provide the information in this example Table format, I am requesting that specific and sufficient documentation that will enable me to do so.

Thank you in advance for your assistance.

EXAMPLE TABLE FORMAT

 Sample School Dist Legal Fee Table.png