

To: Dr. Mike Riggle Board of Education

From: Dr. Kimberly Ptak

Date: Monday, October 22, 2018

Re: Recommended Summer 2019 Capital Projects

Recommendation

It is recommended that the Board of Education authorize District administration to work with ARCON and Associates, the District architect, to develop bid specifications for the following recommended Summer 2019 Capital projects.

Background


Every fall, school and district leadership teams recommend capital projects to the Facility Committee and Board of Education for consideration and approval. Once projects are approved in concept, the district architect (ARCON) develops detailed bid specifications for each project. Projects are put out to bid and actual costs are brought to the Facility Committee for review and the Board of Education for approval. Projects are typically completed during the summer months.

Capital projects are built into the District's annual budget and funded on a "pay as you go" basis. The capital projects budget for the 2019-20 fiscal year will be finalized over the next several months. The following is a summary of recommended projects:

Project Descriptions	
Project and Description	Estimate
GBN Natatorium Ceiling Painting The natatorium ceiling was last painted in 2001 when the larger pool was constructed. Since the painting of the existing ceiling and structure require the pools to be drained, it's the opportune time to perform this maintenance activity is in conjunction with other pool work being performed as part of life safety work. The paint will help preserve the integrity of the existing deck and structure. The scope of work includes the cleaning and preparation of the existing metal deck and joists, priming of areas for application of new paint, and painting of all surfaces and appurtenances with two coats of finish.	\$130,000
GBN Natatorium Surge Tank Replacement The surge tank was installed in 1957 at the time the first pool was built. The tank has considerable corrosion and has been repaired numerous times with fiberglass and is now beyond repair.	\$50,000
GBN Pool Deck Repair The original concrete pool deck was installed in 1957 using a 1" corrugated metal form deck. The deck provided a form for the bottom side of the structural slab to support the weight of the wet concrete and should have been removed after the concrete had set and cured. It has most likely been trapping the humidity and concrete gas from the room directly below the pool deck which is the mechanical room. Over time the metal rebar has rusted and is spalling the bottom side of the concrete slab which impacts the long-term structural integrity.	\$345,000
The corrugated metal deck and all associated pipe work will need to be removed. A wood formwork will be constructed within the mechanical room 8" lower than the bottom side of existing deck. Rebar will be placed and self consolidating concrete will be pumped through drill holes from the pool deck. Temporary shoring (i.e. temporary posts and beams) has been installed as a safety precaution.	

Recommended Summer 2019 Capital Projects Page 3





- Subtotal \$920,000
- Architect and Construction Management Fee \$138,000
 - Contingency \$18,400
 - Estimate Total \$1,076,400